Factory Audit	(Report No.NB1112-0206)
Audit Date: Dec.19.2011	Audited By: Alex Chen
Arrival Time: 13:30	Leaving Time: 17:30
☐ Initial Audit	⊠ Follow - Up Audit

I. GENERAL SUPPLIER PROFILE										
Company Name: Long Xing international Inc. profe	Company Name: Long Xing international Inc. professional pen manufacture									
Address: 10.Pengxi RD, Penglang Town, Kunshan	Jiangsu,China									
Tel: 512-57617620 Fax: 512-57617399	Longx	King International Inc.								
Contact & Title: Angela Lee / Vice general manager Email Address: LSAL7613@pub.sz.isinfor.net	•PROFE	ngela Lee Vice General Manager								
Web: http://www.lungsal.com	Add:10Pengxi Rd. Tel:86-512-57617 Fax:86-512-57617	.,Penglang Town,Kunshan,Jiangsu,China 620 57617611 Mobile:1381289963 7399 Postcode:215333								
	E-mail:LSAL7613@	http://www.lungsalusa.com								
Type of Ownership:										
State Corporation Privately Own	ed 🛛 J	oint-Venture 🗌								
Years in Business: 1997 Annual USD Turnov	er: 1,350,000	Annual Prod. Capacity: 2,500,000								
Range of Products:	Materials Used	:								
Metal pall pen	Metal									
Primary Export Markets:	Primary Custor	ners:								
USA, Europe	BIC									
% Open vs. OEM Items: 20% 80%	Available Catal	ogs?								
	(If yes, please	collect 2 complete sets)								
Do they exhibit at any trade shows? \square Yes \square No	Do they have a	any agents in USA / EU? ⊠ No								
If yes, which ones? PPAI	If yes, please a	advise names and country:								
Personnel met during the audit										
Vice general manager: Angela Lee	Factory Manager	: Zhi Xiao Qing								
General Manager:	Q.A. / Q.C. Manager:Xin Feng									
Marketing Manager: Frank	Production Mana	ger:Zhou Chang Mei								
Engineering Manager:										

Page 2 of 25

,	⊠No
Certification Lab Name: Cer	ertification Date:
II. GENERAL FACTORY FACILITIES	
Small-Sized ⊠ Medium-Sized □	☐ Large-Sized ☐
Total Factory Area (sq m):22000 m ²	
# of Buildings: 1 # of Floors per Buil	ilding: 3
# of Workers in Low Season: 35	# Workers in High Season: 50
# of Employees per Section During:	
(1) Audit:	(5) Quality control: 7
(2) Clerk/Management: 5	(6) Packing: 3
(3) Cutting:	(7) Technic al/Engineering:3
(4) Production: 27	(8) Other:
Prototyping and/or Sample-Making Department	t: Yes 🗵 No 🗌
# of Workers:2 # of Designers:2	Sample Capacity/Mth: 10
R&D Department: Yes ⊠ No □	
Number of Engineers: 2 Types of S	Software: CAD , Photoshop
In-House Tooling/Mold-Making Department:	Yes ⊠ No □
# of Workers: 1	
Type of Machines	<u>Origin</u>
Lathe:	1 China
Milling M/C:	1 China
Drilling M/C:	1 China
Raw Material Country(s) of Origin: Cixi city , W	uxi city
Any Subcontracting: Yes ☐ No ⊠	
<u>Sub-Contracted Parts</u> <u>Purchas</u>	se Lead Time Origin of Part
Was dan Land of Balaka at a will of London	Law.
Vendor Level of Relationship With Sub-Contract	tor:
1	

Page 3 of 25

PROD	UCTION MACHINERY D	ESCRIPTION		
<u>Type</u>		Qty (Set_)	Country Where Built	
Polish	ing machine	4	Taiwan	
Auto I	athe	20	Taiwan	
Printir	ng machine	10	Taiwan	
Cuttin	g machine	3	Taiwan	
Auto S	Spraying line	1	Taiwan	
Drying	g oven	4	Taiwan	
Hand	press	20	Taiwan	
Auto p		3	Taiwan	
Equip	ment Age: New 🗌 Used	\boxtimes How Old: 1	0 Years	
# of P	roduction Lines: 5			
# of V	Vorkers Per Production Line	e: 8-15		
# of P	rod Line QC Supervisors:	0-1		
DAIL	Y PROD CAPACITY			
<u>Item o</u>	description_		Daily Capacity	
Y207			15000	
Embro	oidery Capacity:		Cut & Sew Capacity:	
Silksc	reen Printing Capacity: 15	000	Finished Product Capacity:15	5000
Others	s:			
A. DE	TAILS OF FACILITIES			
1.	Is the plant layout general item:	ally acceptable	to manufac ture the BIC / NORWOOD	⊠Yes / □No
{2}	Does factory have adeque without sub-contracting r		to manufactur e BIC / NORWOOD on work outside?	⊠Yes / □No
{3}			to store ra w materials, packaging, , polybagged pr oducts in master	⊠Yes / □No
4	Are all passages, emerge	ncy exits clear	?	⊠Yes / □No
5	Is there an appropriate a company to conduct pre-		or client?s a pproved inspection ections?	⊠Yes / □No
6.	Is the manufacturing equ	ipment proper	ly maintæ id :	⊠Yes / □No
7	Are maintenance records	of machines a	and equipment d ocumented?	□Yes / ⊠No

Page 4 of 25

8.	Does th	ne factory have a maintenance	repair	rteamo	r equ	ipmen	t:			⊠Y	'es / [□No	
{9}	Machin	es/equipment/fixtures suitable	e to pro	oduce	the i t	em:				⊠Y	'es / [□No	
10.	Is stee	l tooling storage room clean w	ith ade	equate	ecurit	y:				⊠Υ	'es / [□No	
11		actory have appropriate comm I phone utilities.	ıunicati	ion eq	uipme	nt? Iı	ncludi	ng int	ernet,	⊠Y	'es / [□No	
			1	2	3	4	5	6	7	8	9	10	11
Facilit	ies Ratin	ng (11 is best):										×	
书签。	未指定 Item #	Remarks											
错误!	未指定书	签。B. DETAILS OF SAFETY A	ND QUA	ALITY (CONT	ROL							
1.		ory implementing a formal inte tion and has document suppo		uality (c ontr	ol prod	cedure	e for		⊠Y	'es / [□No	
2.	Is there	e adequate Q.C. supervision c	overed	on æll	nifts?					Y	'es / [⊠No	
3.		e an employee training progra g record?	am for	all QC	with	tracea	ble d	ocume	ented	⊠Y	'es / [□No	
4.		tory?s quality control personn s outlined in the quality manua		fied be	e fore	they ¡	perfor	m the	ir job	⊠Y	'es / [□No	
5.		e a Q.C. manager or personne nd is he/she experienced?	l in sur	perviso	ory le	vel to	head	the Q	.C.	⊠Υ	'es / [□No	
6.	Is there	e regular quality performance	review	v?						⊠Y	'es / [□No	
7.	Are the	e QC in-line samples and instru	ıctions	clearl	y labe	led an	d cl e	ar to	read:	Y	'es / [⊠No	
8.	Does th	ne Q.C. team exhibit a strong	sense (ofuqlity	/ conti	ol ow	nersh	ip:		⊠Y	'es / [□No	

Page 5 of 25

9.	Does the factory use up-to-date international Q€tandards?																	
10.	Are the	factory internal QC	repo	orts o	clear	ando	mpr	ehen	sive:					\boxtimes	Yes	/ 🔲 I	Vo	
11.	Is the sa	ampling size for int	ernal	insp	ectio	on an	d tes	ting	ade	quat	e?]Yes	/ 🔲 I	No	
12.		C. staff have adequents, and standar		knov	vledg	je an	d exp	ertis	s e of	BIC	/ No	rwoo	d	\boxtimes]Yes	/ 🔲 I	No	
13.	Is vendor aware of applicable US, Canada and E⊌afety standards? ☐ Yes / ☐ No																	
	If yes, d	etail the standards	they	/ foll	ow: ((Per d	cust	omer	?s re	quire	emer	nt)						
14.	Does factory inform its sub-contractors and supplier s of the applicable, ☐ Yes / ☐ No required to its line of business: Per customer?s req uirement																	
15.	Does factory inform its sub-contractors and supplier s of the applicable,																	
16.		ctory have its own		IIICA	tocti	na de	nt:							∇	1V2c	/ 🔲 l	No.	
10.		lescribe facility: wi				_	•	ipme	ent						4 i C3	<i>,</i> ட.	10	
	, , -	.,	1	2	3	4	5	6	7	8	9	1	1	1	1	1	1	1
			_			-)	,	_			0	1	2	3	4	5	6
QC Ra	ating (16	is best):														×		
	未指定书 tem #							Rem	narks									
		None																
错误!	未指定书3	E. C. INCOMING M	1ATEI	RIAL	S QU	ALIT	Y CO	NTRO	DL									
1.	Is there control?	a documented sup	plier	cer	tifica	tion	proce	ess ir	n plac	ce ar	ıd un	ıder]Yes	/ \(\sigma\)	Vo	
2.	Are inco	ming and outgoing	raw	mat	erials	s pro	perly	regi	ster	ed ar	nd re	cord	ed?	\boxtimes]Yes	/ 🔲 I	Vo	
3.	. Are incoming raw material deliveries properly ientoried and inspected: ☐Yes / ☒No																	
4	Are there adequate inspection instructions and guide lines given to inspectors? \square Yes / \square No																	
{5}	Is the in	spection sampling	size	adeq	uate	and	does	t he	qua	lity c	of rav	v		\boxtimes	Yes	/ 🔲 I	No	

Page 6 of 25

												-
	materials	, components meet all requirer	ments?									
6.	Are there	traceable inspection records?								Yes /	□No	
{7}	Are raw ı	naterials properly labeled, stor	ed, and	tra ce	eable:					Yes /	□No	
{8}		materials inventoried in secure rioration of quality:	storero	oms t	o avoi	id thef	t, loss	s, and	\boxtimes	Yes /	□No	
9.		spection instructions and requires and inspection supervisors:	rements	rea o	lily ava	ailable	to all		\boxtimes	Yes /	□No	
				1	2	3	4	5	6	7	8	9
Incon	ning Inspe	tion Rating (9 is best):								×		
II	! 未指定书 Item #											
	None											
错误!	未指定书签	D. IN-PROCESS QUALITY CO	NTROL									
1.		run quality samples carefully requestions all safety and quality request.						ity sta	ff 🛚	Yes /	□No	
2.	Are spec	fications attached to each work	king mad	chine	for ref	erence	e?			Yes /	□No	
3.	Is numbe	er of inspection staff adequate f	for the p	roduc	tion v	olume	:			Yes /	⊠No	
4.	Are there	routine Q.C. patrol checks on	semi-fir	nished	prod	ucts/p	art <i>§</i>		\boxtimes	Yes /	□No	
5.	Are the C	.C. patrol check intervals adeq	ıuate an	d eff	ective?	?			\boxtimes	Yes /	□No	
{6}	} Does factory effectively identify and separate reje cted lots from accepted											
7.	Does the factory have a corrective action systemor rejected lots: ☐ Yes / ☐ No											
{8}	Is the inspection criteria and/or instructions for t he inspectors clearly legible \square Yes / \square No and easy to follow:											
{9}	Are the a	pproved samples clearly visible	e on eac	h pro	ductio	n line	and c	learly	\boxtimes	Yes /	□No	

Page 7 of 25

	labeled:												
10. Are the inspectors from an outside inspection agency or do they work for the ☐Yes / ☐No factory:													
			1	2	3	4	5	6	7	8	9	10	
In-Pro	cess	Inspection Rating (10 is best):									×		
错误 指定 签。I ^t	: 书 tem			R	emark	S							
		None	None										
错误!	未指定	『中签。E. FINAL INSPECTION											
1.		s factory thoroughly brief the inspectors on the c ustomer?s requirements \square Yes / \square No r to the inspection taking place:											
2		there adequate, clear written crit ectors to follow regarding inspect		instr	uctions	availa	able for	-		∐Yes /	□No		
{3}		s factory have comprehensive an I out, documented, and reviewed						orts th	at [∐Yes /	□No		
{4}		ecords show rejected lots are we ptable lots for re-worked?	ll ident	tified a	nd se	gregat	ed fror	n		∐Yes /	□No		
{5}	stati	there adequate approved sample ons to let inspectors or workers o irements and standards?								☑Yes /	□No		
6	Is th	e sampling size of products for fit?s standards?	nal ins	pectio	n ade	quate	enougl	n to m	eet [∐Yes /	□No		
{7}	Does	s factory perform 100% check on	functi	ion wit	h appr	opriat	e set u	ıp?		∐Yes /	□No		
8.		customer drawings and engineering specifications readily available for \square Yes / \square No lity control and review purposes during inspection:											
9.		bes factory understand its responsibility to collect internal tests during and Yes / Noter production to verify product quality standards and execution:											
10.		the testing equipment calibrated attached?	accord	ling to	s ched	lules w	ith rec	ords a	nd []Yes /	⊠No		
11.	Is fa	gs attached? factory orderly and systematic in its inspection procedures and maintains a Yes / No											

Page 8 of 25

n e														
	proper inspection flow to efficiently log defects and c atch potential issues:													
12.	Does factor inspection r	ry have an effective c results:	orrect	ive ac	tion p	l an d	uring	and a	fter fii	nal	 ⊠Y	'es / [□No	
			1	2	3	4	5	6	7	8	9	10	11	12
Final Ir	nspection Ra	ating (12 is best):											×	
错误! ž	未指定书 em #					Rei	marks							
		None												
F. PAC	CKAGING													
{1}	Is the packaging area clean, organized, and witproper lighting:													
{2}	Are there adequate safeguards to prevent another com pany?s products from \(\simeg\)Yes / \(\subseteq\)No being packed into BIC / Norwood master cartons:													
{3}	Are there adequate controls to prevent any defective o r rejected product from \square Yes / \square No being mistakenly packed with approved product:													
{4}		nished product effect mix-up of items pric				om fi	nished	d prod	luct so	there	e 🛚	Yes /	□No	
{5}		conforming products red from the packaging			ernally	by fa	actory	abso	lutely		\boxtimes	Yes /	□No	
6.	Are produ	icts cleaned before pa	acking	?							\boxtimes	Yes /	□No	
{7}	goods to	icable] Does factory he detect if sewing need (Only applicable to m	dles o	r shar	p meta	al ite ı	ms ha	ve be	en mis			Yes /	□No	
{8}		icable] Is product pac nmediately after pass							ito ma	ster		Yes /	□No	
9.		ed finished product p ting dusty and dirty?										Yes /	□No	
{10}	Are sharp tools absolutely restricted to be used in the packaging area? If \square Yes / \square No unavoidable, is control satisfactory?													
11.		thod of product coun rocedure acceptable t									\boxtimes	Yes /	□No	
12.	Are maste	er cartons sealed with	n adhe	esive t	ape in	neediate	ely aft	er pa	cking:			Yes /	⊠No	

Page 9 of 25

13.		packed master carto ate and weather dar			d in	a co\	vered	d and	l dr y	/ are	a to	prot	ect fi	rom	\boxtimes]Yes	/ 🗆	No	
14.		master cartons iden earance:	tified	d witl	h cus	stom	ier m	arkir	ngs	in ar	ı clea	n ar	nd cle	ear	\boxtimes	Yes	/ 🗆	No	
15.	Are	master cartons put	on p	allets	5?]Yes	/ 🛛	No	
16.	Are	master cartons stac	ked	in go	od c	ondi	tion?)							\boxtimes]Yes	/ 🗆	No	
17.	Are	warehouses locked?	•												\boxtimes]Yes	/ 🗆	No	
			1	2	3	4	5	6	7	8	9	1 0	1 1	1 2	1 3	1 4	1 5		
Packa	ging R	ating (17 is best):													×				
Iten	n #							Rer	nark	s									
		None																	
错误!	未指定	书签。G. NON-CONF	ORM	ING	MAT	ERIA	ALS C	ONT	ROL										
{1}		non-conforming mat ages of production:	erial	s pro	perl	y se _l	parat	ted fr	om (co ni	formi	ng g	joods	s at	\boxtimes	Yes	/ 🗆	No	
{2}	Are ı	non-conforming mat	erial	s cle	arly	marl	ked a	andab	eled	:					\boxtimes	Yes	/ 🗆	No	
3.		proper records main erials:	taine	ed to	sho	w the	e sta	tus c	of n c	n-co	onfor	ming]		\boxtimes	Yes	/ 🗆	No	
4	Is th	ere a written policy	to co	ontro	l noi	n-cor	nforn	ning	mat	erial	s?]Yes	/⊠	No	
5	Is th	e scrapping procedu	ıre e	fficie	nt a	nd sa	atisfa	icto r	у?						\boxtimes]Yes	/ 🗆	No	
6	6 Are there records of scrapped components or products? ☐Yes / ☒No																		
										1	2		3		4		5		6
Non-C	Non-Conforming Goods Rating (6 is best):																		
错误!	未指定							Re	emar	ks									

Page 10 of 25

书签。	Item #											
		None										
错误!	未指定书	E. H. COMMUNICATION, DOCUMENTATIO	N, AND) WOR	K FLOV	w con	TROL	-				
1.		actory management and staff speak and re or effective and efficient communication wi						⊠Yes	/ □No			
2.		es and responsibilities of factory staff clea portunity for communication breakdowns t			o there	e is littl	e if	⊠Yes	/ □No	ı		
3.		actory honor and adhere to customers? CO ne principles and keep all customer produc						⊠Yes	/ □No	1		
4.	Are in-line, final inspection reports kept in master files?											
5.	In case of authorized subcontracting, does factory pr ovide adequate Supervision and guidance to ensure compliance with client?s standards?											
6.	Are there any internal inspection reports on compon ents/parts provided by \square Yes / \square No sub-contractors?											
{7}		actory have very clear policy within its depoint ity to stop production if the products are or					,	⊠Yes	/ □No	1		
{8}		actory understand that all technical informats is confidential and the confidentiality is t				ent?s		⊠Yes	/ □No	1		
Comr	nunicatio	n/Documentation/&	1	2	3	4	5	6	7	8		
Work	Flow Rat	ing (8 is best):							×			
	未指定 Item #		Remar	ks		<u> </u>		-				
		None										
	未指定书籍 applicable	S. I. CONTROL OF SHARP TOOLS (MUST PART)	ASS AL	L) (Fo	rtoy s	and ch	nild pr	oducts	only)			
{1}	Are sha	arp tools attached/tied to the working ber	es:					∐Yes	/ □No			
{2}		actory use a one-piece sharp tool for trimm are not acceptable):	ning p	rocess	(?brea	ak-awa	ıy?	∐Yes	/ □No			
{3}												

Page 11 of 25

	logged when distributed to workers:										
{4}	of sharp tools (even if they are broken) at the end of the working day:										
{5}	Is there a formal pro any production proce					narp too	ols in	□Yes	s / 🗌 No	0	
{6}	[If applicable] Is the sensitivity and operathe log book?						on	□Yes	s / 🗌 No	0	
{7}	If product is not pass the factory takes to							□Yes	s / □No	0	
{8}	Can factory give goo used in the packing a for the sharp tools to	area? If yes, how do	they guara	ntee t	here is	no cha		□Yes	s / □No	0	
Sharp	Tool		1	2	3	4	5	6	7	8	
Rating	(8 is best):										
错误!: 签。 It	未指定书 Remarks										
错误!	未指定书签。J. CLEANL	INESS									
1.	Are the factory floor contamination, and		reasadeand	free of	garba	ge,		⊠Yes	s / □No	0	
2.	Are packing, storage orderly:	e, production areas, a	and asstellynl	ines cle	ean an	d		⊠Yes	s / □No	O	
3.	Are production areas infestation, rodents,	•	d packnaggiar	eas fre	e of in	sect		⊠Yes	s / 🗌 No	0	
4.	Is any pest control u	sed and records ma	intained?					□Yes	s / ⊠No	0	
5.	Are regularly schedu service or handled in	•	•		by a p	rofessi	onal	□Yes	s / ⊠No	0	
6.	Is there daily floor mopping / cleaning scheduled fo r the production, $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$										
7.	Are the work in proc dust and any contan		and polyba	gged p	roduct	s free o	of	⊠Yes	s / □No	0	
8.	Is the packaging area tidy, clean, and free of acontamination? ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐										

Page 12 of 25

9.		there filters or scree amination of produc		all w	indo	ws ii	n the	e pac	kagi	ng a	ireas	s to p	orev	ent		Yes	/ \	No	
10.		trays and cartons us n and stored off the								finis	hed	prod	duct			Yes	/ \	No	
11.		nere a washroom fac luction, assembly, a						n har	nds p	rior	to e	nteri	ing t	he		Yes	/ <u> </u>	No	
12.		s factory packaging ance for workers to es:											ovid	ed		Yes	/ ⊠r	No	
13.	Do employees wear effective hair covering, disposable gloves and protective \square Yes / \square No clothing such as smocks and overcoats:																		
{14}	Are food items, drinks, and chewing gum prohibited in the production, \square Yes / \square No assembly, and packaging areas:																		
{15}	Is tobacco prohibited in production, assembly, and packaging areas and are ⊠Yes / □No there signs posted notifying the workforce:																		
16.		entrance doorways o out dust and conta	-		. Ar	e ve	rtica	l pla	stics	strip	s att	ache	ed to	1		Yes	/ 	No	
17.		s factory have a pro luction floor area:	cedure	in th	ne ev	/ent	of g	lass	brea	kage	e in a	any				Yes	/ <u> </u>	No	
			1	2	3	4	5	6	7	8	9	1 0	1	1 2	1	1 4	1 5	1 6	1 7
Cleanli	ness	Rating (17 is best):										×							
Item			•				F	Rema	arks			•						•	
		None																	
错误!非	卡指定·	书签。K. SPRAY PAII	NTING /	/ HAI	ND-E	DECC) / T.	AMP	O-PR	INT:	ING	CON	TRO	L					
1.		the spray booth lay nd sufficient lighting:		l-org	ganiz	zed,	cletiac	hy,, a	nd h	as p	rope	er an	d			ΣY	es / [□No	١
2.		e the hand-deco fficient lighting:	areas	clea	n, \	vell-	orga	ınize	d, a	ewned	phrep	er a	and			⊠Y€	es / [□No	
3.	Is	there any training p	rogram	for	work	ers	and	is it	ade	quat	e?					□Y€	es / [⊠No	1
4.	Ar	e approval samples	and p	arts	atta	ched	d to	eacl	n wo	n s ta	tion	for	work	er?s		∐Y€	es / [⊠No	١

Page 13 of 25

	reference	e:																	
5.	Are the ir	nspect	ion inte	ervals	s ade	quate?								\triangleright]Yes	/ 🗌 N	lo		
6.	Are inspe	ection	reports	writ	ten?									\triangleright	Yes	/	lo		
7.	Is there instruction			-					-		_			\triangleright	Yes	/ 🗌 N	lo		
8.	Is the de inspector					rk area c	lean,	tidy,	and a	re the	ere sı	ufficie	nt Q0		Yes	/	lo		
9.	Are painted parts properly stored and kept off the fto prevent from \square Yes / \square No getting dirty and dustry:																		
10.	Is there sufficient inspection of sprayed or hamatedcoparts and components prior to assembly:													\triangleright	⊠Yes / □No				
{11}	Is the ventilation system adequate?												\triangleright	⊠Yes / □No					
							1	2	3	4	5	6	7	8	9	10	11		
Spray ar	nd Hand-De	eco Ra	ating (1	l1 is	best)	:									×				
Ite	m #						1	Re	emarl	ks	I			l	I	ı	I		
		Nor	ie																
L. WOR	KING CONI	DITIO	NS																
1.	Are the	emplo	yment	prac	tices	of this fa	cil it ya	afraed no	on-ex	ploita	itive:				⊠Yes / □No				
2.	Are the	worke	ers dorn	nitor	y area	as well-k	ept, c	lead,	secur	e:					⊠Yes / □No				
3.	Are there			r ame	enitie	s such as	on-s	ite po	ost off	fice, p	ublic	telep	ohone	es,	∐Ye:	s / 🛚	No		
4.		-				doctor?s injured				tinwgor	kers	that	fall i	I	⊠Ye	s / 🗌	No		
5.	Does the dormitor			vide	adeq	uate sec	urity	at all	factor	y ent	rance	es as	well	as	⊠Ye:	s / 🗌	No		
6.	Does fac	ctory	orovide	3 m	eals a	a day to v	worke	ers:							⊠Yes / □No				
7.	Is there	ade	quate	fire	evacı	uation in	struc	tions	epotost	learly	and	d vis	ibly		∑Ye:	s / 🗌	No		
		_																	

Page 14 of 25

	through	nou	t the	fact	ory:																		
8.	Are ?su			_						_	uish	ersnda	fire	ho	se	insta	allec	l in		□Y	es /	⊠N	lo
9.	What is Lowest Lowest Any pai	mo ho	nthl urly	y wa wage	ge fo	rwc	rker		 	RMB RMB	tor: 96 7 0	0											
	Is this e What is	-			_			_						ek a	t re	gula	r pa	y:		⊠Y	es /	□N	lo
10.	Do the	wo	rkers	s hav	e at	leas	t one	e da	y of	f in :	seve	n:								⊠Y	es /	□N	lo
11.	Are hou	urs	work	ced a	adequ	atel	y do	cum	ente	ed (e.ign,	etcard	ls)?							□Y	es /	⊠N	lo
12.	Is over	tim	e vo	lunta	ary?															⊠Y	es /	□N	lo
13.	Do emp	oloy	ees	rece	ive d	etail	ed p	ay s	tubs	s?										⊠Y	es /	□N	lo
14.	Are em	plo	yees	peri	mitte	d to	leav	e er	nplo	yme	ent a	gtem	g re	aso	nab	le n	otice	e?		⊠Y	es /	□N	lo
15.	Are all	iow	kers	pro	vided	a w	ritte	n er	nplo	yme	enttr	aoct?								⊠Y	es /	□N	lo
16.	Factory	⁄ do	es n	ot al	low t	he u	se o	f co	rpor	al p	unisl	ntnæn	phy	sica	l co	erci	on?			⊠Y	es /	□N	lo
17.	Are per	sor	nel	train	ed or	n fire	pre	ven	tion	and	enggne	ncy p	repa	ared	dnes	s pl	ans	?		⊠Y	es /	□N	lo
18.	Are the respirat															gogg	gles	or		ΠY	es /	⊠N	lo
						1	2	3	4	5	6	7	8	9	1	1	1	1	1	1	1	1	1
Work Con best):	iditions F	Rati	ng (18 is	3										0	1	2	3	4 ×	5	6	7	8
Item	n #										F	Rema	rks										
		No	one																				

错误!未指定书签。SUMMARY OF POINTS A	CHIEVED				
SECTION	Minimum Points Needed	Maximum Points Possible	Total Points Achieved		
A. Facilities	6	11	10		
B. Safety and Quality Control	8	16	14		
C. Incoming Materials Inspection	5	9	7		
D. In-Process Quality Control	5	10	9		
E. Final Inspection	6	12	11		
F. Packaging	7	15	13		
G. Non-conforming Materials	3	6	4		
H. Communication/Documentation/Flow	4	8	7		
I. Control of Sharp Tools	8	/	/		
J. Cleanliness	9	17	10		
K. Spray Painting/Hand-Deco/Tampo	6	11	9		
L. Working Conditions	9	18	14		
	Total Points Achie	eved	108		
	Maximum Points	Possible	133		
	Overall % Rating		81.2%		

Note:

- All individual sub-groups must meet minimum points needed.
- Overall rating must be no less than 70%.
- Items with { } brackets are critical points. ARNO? audit result for these items must be taken seriously and requires special management consideration of vendor.
- Total Critical { } items to be rated: <u>26</u>Total Critical { } items to have failed: <u>0</u>

Grade:	Outstanding	-	Over	95%
--------	-------------	---	------	-----

Excellent - 90% - 95%
Very Good - 85% - 89%
Good - 80% - 84%
Average - 70% - 79%
Needs Improvement - 61% - 69%
Not Recommended - Below- 60%

Pictures:

Buildings (Including factory gate and all buildings)










Business License and Certificate (i.e. ISO and inte rnational certificate if any)





Factory Floor Plan



Factory Organization Chart

No

Office and Show Room









Staffs and Workers

Page 19 of 25



Dormitory	
No	
Contract (Turkyding bookh license)	
Canteen (Including health license)	
No	

Warehouse (i.e. Raw materials and finished goods)









Tooling Room









Machines (Including power generator, molding and pr oduction if any)

















Production Area













Packaging Area





Copyright? BIC Advertising & Promotional Products A sia Ltd. - Rev. 0

ality D	epartme	ent , Insp	pectio	n Process &	Repo	rts					
	电镀检验标	示准					成品	检验报告	与单		
					174.50	1 0612057	客户信号	1 1/2 1		20/0 #	2000 PKS
					品老	Y209		kī - leli	•		2000
й В	等 级 A 级	B & C	級		40			批化	建设是企业	批告 (2	女) 抽些数
1、耐伤、排 可按5		该受<1.5mm 1-2/零件未 50			块头	AA	ВС	(支)	32	3201 10	
46; ATE 45;		J≥1.5mm ≥1/零件見 同B章	8		並大 产女	The second second second second	. 0% 0. 5%	281 500	50 80	1000173	5000 315
2、和和	是<0.5mm 1-2/零件 可报	炎受<1.5mm 1-2/零件 阿B当			松歌		0% 3.5%		125,	15000176	
3、电镀不良 不可5	≥0.5mm ≥1/零件 MA. 呈現明显雾状 同 A	J≥1.5mm ≥1/零件	量現事状			检 验	结	果		数	*
2 36	E現锈斑 同A		177		万·多	不	良原因錯	进	2 and	新大	产量 發放
全 5、脏污 表面为	光清,不可有污点	THE REAL PROPERTY.	明是 0.3m 距离		2 4 117 6	(2 Janu ¹⁴⁵ : \$162 \$ Janu ¹⁴⁵ : \$463	功不是3%				×
7、色装 与样本	PE A	数 目视不过 上村本3			3 4						2000
8、復料 不得有			STATE OF THE PARTY		5 ******	4. t c x x	p 1		Tone		
10/8/2018		7 A- M						Pancut (15	验报生》	9.80	
	成品检验排	B	H 20 H			2 - 1		Report (检	17.14	Date (BR	2009/ 05 //
0611140	客户维号)) [6]	103B WE	low for		PO# (分单号) Pen color(定颜色)	0703163		ored over 24 flours	BIC (是在平台24小司	QTY	(#18) 64se)
727		1 11			ITEM(#8)	Y227 Lot Size = 15073		sple Size(#0/##1)	Lot Size供量/3	Sample S	ze mik to
等级	(支)					150-280 281-500		32 50	3201-10000 10001-3500	0 3	35
A* A 0.0% 0.0%	B C 150°28 6 0.0% 0.5% 281°50		00 200			501-1200 1201-3200		80 125	35001-15000 150001-5000	00	500
E 0.5% 1.0% k 1.5% 2.5%	1.5% 2.5% 501~120	90 80 35001 1500			CHAR, CLASS (特有) Inspection item (4):	能拘接) San Fi	nple Size((clicity)) xed sampling 10 (Microsor)	1 10000	nderd (影階) rfect (概全部周	Result()
检	验结果	数	*			Date of refill (地方 Refill) Color (地方	FI	xed sampling 10 (固定批评)	Zero de	efect (高金田道	0.0000000000000000000000000000000000000
	不良原因描述	安大 产	童 松松					0 iii oxed sampling 10	pass,>=1-retu unqualified.	test another 8) pes. 音不合格,再
mps 砂格:毛	東):15pm E四不良	E: 2PK			Critical(美權)	Writing (#30	D Fi	(景定地符) 行	urass >=1-retu	artic	NEW AND ASSESSMENT
							F	it	funqualified.	test another 8	pcs。 5不会格,再
248 組織自治	高江志 / open	不改数量			A	Tape test (20 %)	AND DESCRIPTION OF THE PERSON NAMED IN	ixed sampling 30 名 《重定程序》	0-pass.>	-1-return (96)	12)
数/抽验箱数	強強軟量	允许数量		' '		Parte come office	oleg)	203	()-pass,>	=1-return (ot	
	L			, 1,			- >11 -	LA MA I		C4 3 8 8 8	S. C.
成	品检验(外观)	标准				烤沒	进科	检验标准			B 1100
	等 级	要 東			* 項 目		19	级要	来		
項目	A &	B # (C 80		大 1、刮伤	A 级 可接受<1.5mm 1-		B 9 可接受<3.0mm		C f	ž.
	是<1.5mm。2-4/毛木光明 見	107 101	級			例 不可接受≥1.5mm		不可接受≥3.0	mm 1/零件	阿B酸	
T 160-45		AJ≥3.0mm、≥1/笔见假 接受<1.5mm。2-4/笔			_	可接受<0.5mm 1-		見個 可接受<1.5mm	1-2/零件	2000	
MAJ>	≥0.5mm, ≥1/% M2	AJ≥1.5mm. ≥1/笔			般 3、颗粒	例 不可接受≥0.5mm	1/零件享得	未見側 不可接受≥1.50	mm 1/零件	同B级	136 13
TI 40-16	September 2 ACT to 10 ats	A 级 同 A 接受<1.5mm, 2-4/笔未			验 外 4、油点	不得見朝(素材原色)	THAM	見網 阿A級		同A鉄	
1、制伤	>0.5mm, ≥1/笔见钢 M/	AJ≥1.5mm, ≥1/笔见铜	W.		夏 5、变形	不得有变形		可接受<1.5mm 不可接受≥1.5m		阿B級	
2, 50/12		接受<1.5mm。2-4/笔 AJ≥1.5mm。≥1/笔	0		6、 <u>色差</u> 7、 <u>廃</u> 面、阴阳	与样板对比		与样板对比		与样板对比可接受 0.3	
3、电镀不良 不可复	呈明显篡状	A 级 部分s	吐坐现雾状		面、气泡	可接受 0.2m 距离目初	光不明显	同 A 级 11-25um, 珍珠、	A007 50 00	视不明显	
The second second			兰型模糊		1、 股州	25-50ua		膜厚: 11-25us 花 A 级:11-45us	. 水洗、网	11-35um- 面、橡皮漆	
W & 可接电	● 0.2m 防富日均不耐息 图	A 489	是 0.3m 長高	· I	2、例签为	用 3M 胶布贴 lain.	立即擴去,	E01 + 402	1020.55	22 A 45	
All Control of the last					and the latest terminal to the			- C - C - C - C - C - C - C - C - C - C	245 (000000	(1) (Sec. 1)	
车制	制成型五金零件	牛检验标准				塑胶	零件核	企验标准			
								18 8 18 1			
THE REAL PROPERTY.					种类项目	A III		等級要求 B級		C级	
項目	MARKET STATE OF THE PARTY OF TH	亨級要求 B級	C 级		1、毛边	不可有毛边		同A级		可有轻微毛	4
车修毛边 不	A 级 可有毛边	同A级	C 级 同A级		2、射出不良	不得有射出不良	SHA	同A级		可有轻微射	B不良
	得有车刀痕	同A级	可有轻微车刀痕		3、模痕	不得有模痕 可接受<0.3mm。	1.2/常件	同 A 级 可接受<1.5mm	1.2/李件	可有轻微模	W.
下前错误 不	得错災	間A級	同A级		性 4、刮伤	可接受<0.3mm。 MAJ≥0.3mm。1/		MAJ≥1.5mm		同A袋	
四綱(姓孔)	接受<0.5mm 1-2/零件。	可接受<1.5mm 1-2/零件。	同B级		验 5、颗粒	可接受<0.3mm,	Water Comment	可接受<1.5mm	N. P. C.	同A級	
	AJ≥0.5mm ≥1/\$#	MAJ≥1.5mm ≥1/零件			6、色差	MAJ≥0.3mm, 1/ 与样板对比	本件	MAJ≥1.5mm。 同 A 级	1/零件	阿A彼	
刻伤	接受<0.5mm 1-2/零件	可接受<1.5mm 1-2/零件。	同B級		1、服料耐冷		PC(本色) F	PC(集色) ABS	POM	PCTA	PMMA
	AJ≥0.5mm ≥2/零件	MAJ≥1.5mm ≥2/零件			超越	冲击强度(J/m)	300	60 100	40	150	30
W TO THE LOCAL		The second secon	污占不明显		The second second second	AA AA 20 AA A	40	20 20	50	35	30

Testing Equipment









Safety, Fire Prevention and First-aid





Page 25 of 25





Other







全日制劳动合	同书
用人单位(甲方): 整当公司	2 to 1.18 5.18 7.19 1 7 7 2 1 1 1 1 1 1 1
用人单位住所: 查到達沒少於 /0号	
工商登记: 注册类型:	*.货
劳动合同履行地:	er Canal
法定代表人(负责人): 許達 建	TA STANSAN
RAME OF THE PARTY	
劳动者 (乙方): 等 任 性别: 女	文化程度: _ セデ

- End -